

SPOT WELD DRILL



The Tool to use for drilling High Strength Steel!

Operates at 1200rpm or less. Drill bits will last longer.
Use for removing spot welds on all flanges.
Comes with removable „G-clamp“.
Adjustable depth to ensure there is no drilling in second panel.
To extend the life of the drill bit, use the center punch and the special cutting oil.

401 001 Spot weld drill